

# Assembly Instructions, Line of Sight Filler Plate & Filler Panel: LOS3-FC-36-, LOS3-FC-42-, LOS3-FPB2B-



## Parts Included

**A** Line of Sight Filler Plate  
Qty: 1 or 2

**B** #10 × ½" Pan Head Screws  
Qty: 16

Two pieces: 60", 66" & 72" Workcenters  
or  
One piece: 36", 42", 48" & 54" Workcenters


**C** Line of Sight Filler Panel  
Qty: 1

## Required, Sold Separately

Two Line of Sight Assembled Chassis' of the same size with Desktop

## Tools Required

Drill/driver or Phillips screwdriver with #2 tip



**Note:** These instruction assume that you've purchased and assembled at least two Line of Sight Electric Workcenters and you want them attached back-to-back. For back-to-back configurations, End Panels and Filler Channels are required.

For side-to-side configurations systems, especially with shared power, Ganging Brackets are required and sold separately.


**Use at least two people to move Line of Sight Workcenters.**




## 1 Install Filler Plate on Workcenter

Situate all Workcenters in their approximate final locations, anticipating that you will require a bit of working room between the Workcenters to add the Panels.


- 1.1** Power all Workcenters and raise all the Monitor Lifts. You will need to access the screw holes located on the Chassis under the Monitor Lid.
- 1.2** Insert the Filler Plate (A) into the gap between the Top Bracket and Chassis, under the open Lid.
- 1.3** Attach with two #10 × ½" Pan Head Screws (B) from above in the OUTER screw holes.
- 1.4** Hold the lid up and press the down arrow on the control to lower the Monitor Lift so you can access the CENTER screw hole and attach with one #10 × ½" Pan Head Screws (B).



Button Side View




View from above



View from below

## 2 Attach Workcenter with Filler Plate to Second Workcenter

- 2.1 CAREFULLY push the second workcenter into position and guide the Filler Plate (A) into the gap between the Top Bracket and Chassis, under the open Lid.
- 2.2 Attach with three #10  $\times \frac{1}{2}$ " Pan Head Screws (B) from above as in **Steps 1.3 & 1.4**.



## 3 Install Filler Panels

With all your Workcenter pairs joined back-to-back with the Filler Plates(A), you will need to finish your configuration by adding Filler Panels(B) to the very ends of your rows.

**Note:** If you are building rows, you must attach side-by-side Workcenters with the Ganging Brackets (sold separately). This can be done either before or after the Filler Panels are attached, but it **MUST** be done to comply with electrical regulations.

- 3.1 Insert the Filler Panel (B) UNDER the lip of the Filler Plate(A). Attach with one #10  $\times \frac{1}{2}$ " Pan Head Screw from above. Magnets will hold the lower portion in place.
- 3.2 Repeat for other side.

