

Installation and Assembly - Heavy Duty I-Beam Clamp with Decoupler



This product is intended for use with UL Listed products and must be installed by a qualified professional installer.

Note: Read entire instruction sheet before you start installation and assembly.

Model:
DCT500


For customer service call 1-800-729-0307 or 708-865-8870. Visit the Peerless Web Site at www.peerlessindustries.com.

Before you start make sure all parts shown below are included with your product.

Maximum load rating 600 lbs (272 kg) Combined weight to all attached hardware and components is not to exceed 600 lbs (272 kg).

Parts List	PART #	QTY.	DESCRIPTION
A	128-0422	1	tray
B	128-1194	2	clamps for i-beam
C	520-1018	4	1/2-13 X 2" square head bolt
D	520-1019	4	1/2-13 X 1" carriage bolt
E	530-1008	4	lock nut 1/2-13
F	540-2005	4	flat washer 1/2-13

Note: Some parts may appear slightly different than illustrated.



⚠ WARNING

- If multi-display system, in combination with components exceeds 600 lbs (272 kg) it therefore exceeds the maximum load. Heavy Duty I-Beam Clamp with Decoupler will not safely support a combined load which exceeds 600 lbs (272 kg).

1 **Note:** For each step see corresponding illustration. Attach brackets (B) to tray (A) using four 1/2-13 X 2" square head bolt (C), washers (F), and lock nuts (E). Do not fully tighten. Start four 1/2-13 X 1" carriage bolts (D) into clamps (B).

1-1 Adjust clamps (B) securely around I-Beam. Tighten (C,F,E) securely. Tighten four bolts (D) securely. Attach the extension column according to the instructions provided with it. Use a level to make sure the column is plumb and make adjustments as necessary.

