


Assembly Instructions: Fundamentals Desk Light FD-DL10-S


Parts Included



No tools are required to assemble Fundamentals Desk Light


1 Attach Light Arm (A) to Light Base (B)

Align Light Arm (A) bottom hole with Light Base (B) pin and attach. Apply pressure until arm *snaps* onto base.



2 Attach Light Head (C) to Light Arm (A)

Align Light Head (C) back hole with Light Arm pin and attach. Apply pressure until Light Head (C) snaps onto arm.




3 Attach Transformer & plug into outlet

Connect cord from Transformer (D) to port on back of Light Arm (A) near the base. Plug Transformer into all outlet.



Note! If attaching light to adjustable height worksurface, raise worksurface to maximum height before positioning fixture to ensure that cord will reach the outlet when worksurface is raised.




✓ Support

Replacement Transformer: TR-12240500-A-SF3.5
Transformer specifications: 12W, 24V, 0.5A, Type-A Plug, Straight Female - 3.5MM Connector


Technical Support: Please call Workrite Technical Support while at the Workrite product.
(800) 969-9675 option 2.

On/Off and dimming



- ON/OFF:** To turn the Fundamentals Desk Light on or off, simply touch the end of the Light Head. This is a Touch-Sensitive Switch and it will react to a light touch.
- DIMMING:** To dim the Fundamentals Desk Light, touch and hold the Light Head Touch Sensitive Switch. As you hold the light will slowly dim. Release you finger from the sensor when you have reached the right dimming level.
- RESET:** To reset the dim level, simply touch the Light Head touch sensitive switch to turn the light off then repeat the on/off or dimming process.

Swivel and rotate



The Fundamentals Desk Light Head swivels a full 360°. Simply twist the head in the direction you wish to have light or to minimize glare.

The base also rotates a full 360° to place the light just where you need it.