


CAUTION:


Mechanism can rise quickly with no equipment in place. User equipment must be properly installed, prior to height adjustment. Failure to do so may result in personal injury and/or property damage.



Winston Lift™ Single

Parts List


A Rectangular Spacer 2x
701544



B 1/2-13 x 3" Socket Set Screw 2x
701126



C Work Surface 1x
413878-WHT (white)
413878-BLK (black)



D M8 Screws 4x
714262




E 5mm Allen Wrench 1x
710838




F Vertical Column 1x
113389



G Monitor Tilter 1x
414291



H Monitor Bracket 1x
414250



I M6 x 12mm Screw 1x
713217



J 10-32 x 3/8" PhPHS (4-pack) 1x
702281



K 75/100 mm VESA Adapter 1x
105587



L M4 x 12 mm PhPHS (4-pack) 1x
702096



M Column Cap 1x
113496




N 7/32" Allen Wrench 1x
701127



O 3/32" Allen Wrench 1x
700146





P Cable Manager 1x
113842




Q 4mm Allen Wrench 1x
709877




1



2




3




i Adjustment feature

Left-right tilt work surface adjustment can be made by tightening the (4) outer hex head screws with a 4mm Allen Wrench (item Q).


4




5




6




7



8





9






CAUTION:


Mechanism can rise quickly with no equipment in place. User equipment must be properly installed, prior to height adjustment. Failure to do so may result in personal injury and/or property damage.




7/32"




Height adjustment



Slide lever into unlock position.




Raise/lower to desired height.



Slide lever into lock position for maximum stability.

11



12

