


# Assembly & Installation Instructions: Hanging Pedestal Power Supply ACC-HPED-PWR-B

**Workrite**  
ergonomics®

## Included:




ID	Part Name	Qty
A	Hanging Pedestal Power Supply	1
B	Cable Clips	3

## Required, Sold Separately:

Desk or Table  
Hanging Pedestal


## Tools Required:



#2 Phillips Screwdriver


## 1 REMOVE DRAWER

Completely remove drawer  
from main body of pedestal.




## 2 REMOVE PLATE FROM MAIN BODY

- 2.1 Remove plate from Main Body by removing x2 Phillips screws



## 3 PLACING POWER SUPPLY

- 3.1 Insert power supply in cutout and secure with x2 Phillips screws which were removed in Step 2



## 4 SECURING CABLE

4.1 Secure power supply power cord along top of Main Body with cable clips

4.2 Insert drawer back into Main Body

 **KEEP CABLES AWAY FROM ANY MOVING PARTS**

