


innovative\_ design works



Innovative Ergonomic Solutions companies

## **7000**Installation Instructions



Innovative Ergonomic Solutions


800 524 2744 customerservice@team-ies.com team-ies.com HAT Collective 408 437 8770 cs@hatcollective.com hatcollective.com

А	Top Down Mount 1x 8524	F 10-32 x 3/8" FPhMS w/Lock Patch 1x 705198	K 7/32" Allen Wrench 1x 701127
В	Monitor Tilter 1x 8500 Tilter	G Forearm Cable Cap 1x 115584	
C	Quick Connect VESA Plate 1x	H Cable Cap 1x 114810	
D	M4 x 12mm Phillips Pan Head Screw (4-pack) 1x 702096	I 1/8" Allen Wrench 1x 701312	
 E	Dog Washer 1x 105189	J 3/32" Allen Wrench 1x 700146	






Desk thickness up to 1.5" (3.8 cm)






Desk thickness up to 1.5" (3.8 cm)





OR




2

























TILTER FRICTION ADJUSTMENT



### **IMPORTANT!**

- · Monitor must be on arm
- · Arm must be in mount






If the arm **drifts upward,** turn the adjustment screw clockwise.




If the arm **drifts downward,** turn the adjustment screw counter-clockwise.

Depending on the weight of your monitor, you may have to make 15-20 turns.




adjustment screw as shown.














Innovative Ergonomic Solutions companies


### **SWITCH**


Installation Instructions | Horizontal Positioning











# SWITCH<sup>™</sup> Parts List

ITEM	DESCRIPTION / PART NO.	QUANTITY
A O	Rotation Prevention Bracket 106271	1
B	<b>10-32 x 1/2" FPhMS</b> 709129	4
C	<b>M4 x 12mm Pan Head Screw</b> 701153	8
D	<b>75/100mm VESA® Adapter</b> 109464	2